


# INTELLICHLOR®

Replacement Parts



## **INTELLICHLOR®**

### **Replacement Parts**

No.	Part No.	Description	Part No.	Includes
1	H-52-0595	Replacement Union Set	2	
2	520735	Flow Switch replacement kit	1	

#### **Not Shown**

H-52-0884	Spacer Cell (for start-up or winterization)
520670	Acid Washing Kit (incl. Closed end union cap, o-ring and coupling nut)
521147	Gasket Kit - Set of 10 o-rings
H-52-0594	Diagnostic Wand

Rev. 08/2011